

Installation Guide

for *Kodak* i1400 Series Scanners

Package Contents

- *Kodak* i1410, i1420 or i1440 Scanner
 - Input tray
 - Output tray
 - USB 2.0 cable
 - Power cord bundle
 - Power supply
 - Sample Cleaning Kit
- Welcome Folio including:
- Installation and application CDs
 - Registration card
 - Printed User's Guide, English
 - Printed Quick Tips Guides
 - Service Contact Sheets
 - Miscellaneous flyers

NOTE: Additional instructions for the steps below can be found in the User's Guide and other supporting documentation.

1

Attaching the input tray


- Align the input tray pins with the holes in the scanner brackets.
- Insert one side first then slide and push in the other side.



2

Attaching the output tray

- Insert one of the pins on the side of the output tray into the hole.
- Align the other pin at the hole and lightly push the tray into the other hole.



3

Installing the software

- Insert the *Kodak* i1400 Series Installation CD in the CD_ROM drive. The installation program starts automatically.
- Select **Install Scanner** software.
- Follow the on-screen instructions to install the TWAIN and ISIS drivers and the *Kodak* Scan Validation Tool.

IMPORTANT:

Install the *Kodak* Driver Software on the host PC before you connect the scanner.

4

Connecting the USB cable



- Attach the B end of the USB cable to the scanner USB port.



- Attach the A end of the USB cable to the USB port on your PC.

5

Connecting the power cord

Use only the power supply that was provided with your scanner.

- Select the appropriate AC power cord.
- Attach the power cord for your power type to the power supply.



- Plug the output power cord from the power supply into the power port on the scanner.
- Plug the other end of the power cord into the wall outlet.

6

Turning on the power

- Press the power switch on the side of the scanner to turn the scanner on.



NOTE: The scanner will go through a series of self tests and the green LED indicator will flash. When it is finished and ready to scan, the indicator will stop flashing and stay lit.

If the green indicator light is not steady, refer to the User's Guide for more information.

7

Scanner will be recognized by the software

Your operating software will now auto detect the scanner. The New Hardware Wizard will be launched. Follow the on-screen instructions.

NOTE: If a flatbed is attached, the New Hardware screen may be displayed once for the scanner and once for the flatbed.

When the scanner has been recognized, your scanner has been installed successfully.

8

Setting up a test scan

- Place a document to scan in the input tray.
- Select **Start>All Programs>Kodak>Document Imaging>Scan Validation Tool**. The Scan Validation Tool dialog box will be displayed.
- Select **TWAIN** (or **ISIS**) for the Driver Types and **Kodak Scanner: i1410** or **i1420** as the Driver. The Scan Validation Tool dialog box is displayed:



9

Scanning an image/verification

- If the image viewer window is not open, click one of the View buttons.
- Click the button. The scanned document will be displayed in the image viewer window.
 - If the document is scanned correctly, the installation and verification of your scanner is complete. **Congratulations!** You may now install the third-party scanning application software you intend to use with your scanner.
 - If the document did not scan correctly, refer to the User's Guide for *Kodak* i1400 Series Scanners for more information.

For more information about *Kodak* Scanners and *Kodak* Capture Software visit our website.

www.kodak.com/go/docimaging

EASTMAN KODAK COMPANY
343 State Street
Rochester, NY 14650 U.S.A
A-61552 / Part No.9E4699
January 2007
© Kodak 2007, TM: Kodak

Kodak